





INSTALLATION GUIDE

I404T

Components List



1 Cooler x 1



2 Thermal Grease x 1




3 Screws x 4




4 Unterlegscheiben x 4

Intel LGA 1156/1155/1151/1150



STEP 1

Apply a thin layer of thermal grease to the CPU surface.



STEP 2

Put the cooler onto the CPU; insert the screws through the washer from the back of the motherboard and fasten to secure.