



M704
Installation Manual

Component List



Cooler (incl. fan) x1



LGA1150 Bracket x1



LGA1150 Bracket x1



LGA2066/2011 Bracket x2



Bracket Mounting Screws x4



AMD Bracket x2




Thermal Grease x1



Fan Mounting Clip x4

Intel LGA1150/1151/1155/1156



STEP 1

Mount the LGA1150 Bracket onto the cooler fan with 4 screws.



STEP 2


Stick the LGA1150 Bracket onto the back of the motherboard.

Intel LGA1150/1151/1155/1156



STEP 1


Apply a thin layer of thermal grease to the CPU surface.



STEP 4

Put the cooler onto the CPU, and thread the screws into the backplate to secure.

Intel LGA2066/2011



STEP 1


Mount the LGA2066/2011 Bracket onto the cooler fan with 4 screws.



STEP 2

Apply a thin layer of thermal grease to the CPU surface.


Intel LGA2066/2011



STEP 3

Put the cooler onto the CPU, and thread the screws into the backplate to secure.

AMD AM4/AM3(+)/FM2(+)/FM1



STEP 1

Remove the original AMD plastic retention frame, but keep the original backplate.



STEP 2

Mount the AMD bracket onto the cooler fan with 4 screws.

AMD AM4/AM3(+)/FM2(+)/FM1



STEP 3


Apply a thin layer of thermal grease to the CPU surface.



STEP 4

Put the cooler onto the CPU, and thread the screws into the backplate to secure.

Fan Mounting



Mount the fan onto the backplate with the fan clips.